



AD-A101 230

INTEGRATED INFORMATION SUPPORT SYSTEM (IISS) VOLUME 3 1/1  
IISS CONFIGURATION. (U) GENERAL ELECTRIC CO SCHENECTADY  
NY PRODUCTION RESOURCES CONSU. N MARVIN 01 NOV 85

UNCLASSIFIED

OM620124001 AFHAL-TR-86-4006-VOL-3-PT-11 F/G 12/5 NL






MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

**AFVAL-TR-86-4006  
Volume III  
Part 11**

**AD-A181 230**

**INTEGRATED INFORMATION  
SUPPORT SYSTEM (IISS)  
Volume III - IISS Configuration Management  
Part 11 - VAX Installation Guide**



**General Electric Company  
Production Resources Consulting  
One River Road  
Schenectady, New York 12345**

**Final Report for Period 22 September 1980 - 31 July 1985  
November 1985**

**Approved for public release; distribution is unlimited.**

**MATERIALS LABORATORY  
AIR FORCE WRIGHT AERONAUTICAL LABORATORIES  
AIR FORCE SYSTEMS COMMAND  
WRIGHT-PATTERSON AFB, OH 45433-6533**


**DTIC  
ELECTE  
JUN 16 1987  
S E D**

# NOTICE

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto


This report has been reviewed by the Office of Public Affairs (ASD/PA) and is releasable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nations.

This technical report has been reviewed and is approved for publication.

  
DAVID L. JUDSON, PROJECT MANAGER  
AFWAL/MLTC  
WRIGHT PATTERSON AFB OH 45433

5 Aug 1986  
DATE

FOR THE COMMANDER:

  
GERALD C. SHUMAKER, BRANCH CHIEF  
AFWAL/MLTC  
WRIGHT PATTERSON AFB OH 45433

7 Aug 86  
DATE

"If your address has changed, if you wish to be removed from our mailing list, or if the addressee is no longer employed by your organization please notify AFWAL/MLTC, W-PAFB, OH 45433 to help us maintain a current mailing list."

Copies of this report should not be returned unless return is required by security considerations contractual obligations, or notice on a specific document.

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE

## REPORT DOCUMENTATION PAGE

1a REPORT SECURITY CLASSIFICATION Unclassified		1b RESTRICTIVE MARKINGS	
2a SECURITY CLASSIFICATION AUTHORITY		3 DISTRIBUTION AVAILABILITY OF REPORT Approved for public release; distribution is unlimited.	
2b DECLASSIFICATION/DOWNGRADING SCHEDULE			
4 PERFORMING ORGANIZATION REPORT NUMBER(S)		5 MONITORING ORGANIZATION REPORT NUMBER(S) AFVAL-TR-86-40 06 Vol III, Part 11	
6a NAME OF PERFORMING ORGANIZATION General Electric Company Production Resources Consulting	6b OFFICE SYMBOL (If applicable) AFVAL/KLTC	7a NAME OF MONITORING ORGANIZATION AFVAL/KLTC	
6c ADDRESS (City, State and ZIP Code) 1 River Road Schenectady, NY 12345		7b ADDRESS (City, State and ZIP Code) WPAFB, OH 45433-6535	
8a NAME OF FUNDING/SPONSORING ORGANIZATION Materials Laboratory Air Force Systems Command, USAF	8b OFFICE SYMBOL (If applicable) AFVAL/KLTC	9 PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER F33615-80-C-5185	
8c ADDRESS (City, State and ZIP Code) Wright-Patterson AFB, Ohio 45433		10 SOURCE OF FUNDING NOS.	
		PROGRAM ELEMENT NO. 78011F	TASK NO. 7500
		WORK UNIT NO. 62	WORK UNIT NO. 01
11 TITLE (Include Security Classification) (See Reverse)			
12 PERSONAL AUTHOR(S) Marvin, Nancy			
13a TYPE OF REPORT Final Technical Report	13b TIME COVERED 22 Sept 1980 - 31 July 1985	14 DATE OF REPORT (Yr., Mo., Day) 1985 November	15 PAGE COUNT 20
16 SUPPLEMENTARY NOTATION ICAM Project Priority 6201		The computer software contained herein are theoretical and/or references that in no way reflect Air Force-owned or -developed computer software.	
17 COSATI CODES		18 SUBJECT TERMS (Continue on reverse if necessary and identify by block number)	
FIELD	GROUP	SUB GR	
1308	0905		
19 ABSTRACT (Continue on reverse if necessary and identify by block number) This installation guide provides step-by-step instructions for installing IISS from the VAX release tape onto any VAX containing the prerequisite system hardware and software.			
20 DISTRIBUTION AVAILABILITY OF ABSTRACT UNCLASSIFIED/UNLIMITED <input checked="" type="checkbox"/> SAME AS RPT. <input type="checkbox"/> DTIC USERS <input type="checkbox"/>		21 ABSTRACT SECURITY CLASSIFICATION Unclassified	
22a NAME OF RESPONSIBLE INDIVIDUAL David L. Judson		22b TELEPHONE NUMBER (Include Area Code) 513-255-8976	22c OFFICE SYMBOL AFVAL/KLTC

DD FORM 1473, 83 APR

EDITION OF 1 JAN 75 IS OBSOLETE.

Unclassified

SECURITY CLASSIFICATION OF THIS PAGE

11. Title

Integrated Information Support System (IISS)  
Vol III - IISS Configuration Management  
Part 11 - VAX Installation Guide

A S D 86 0011  
9 Jan 1986

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	



✓ The Integrated Information Support System is a test computing environment used to investigate and demonstrate and test the concepts of information management and information integration in the contexts of Aerospace Manufacturing. Specifically, IISS addresses the problems of integration of data resident on heterogeneous databases supported by heterogeneous computers, interconnected via a Local Area Network. A common Data Model is maintained and provides the mechanism required to integrate the data.

→ to 1473

## PREFACE

This installation guide covers the work performed under Air Force Contract F33615-80-C-5155 (ICAM Project 6201). This contract is sponsored by the Materials Laboratory, Air Force Systems Command, Wright-Patterson Air Force Base, Ohio. It was administered under the technical direction of Mr. Gerald C. Shumaker, ICAM Program Manager, Manufacturing Technology Division, through Project Manager, Mr. David Judson. The Prime Contractor was Production Resources Consulting of the General Electric Company, Schenectady, New York, under the direction of Mr. Alan Rubenstein. The General Electric Project Manager was Mr. Myron Hurlbut of Industrial Automation Systems Department, Albany, New York.

Certain work aimed at improving Test Bed Technology has been performed by other contracts with Project 6201 performing integrating functions. This work consisted of enhancements to Test Bed software and establishment and operation of Test Bed hardware and communications for developers and other users. Documentation relating to the Test Bed from all of these contractors and projects have been integrated under Project 6201 for publication and treatment as an integrated set of documents. The particular contributors to each document are noted on the Report Documentation Page (DD1473). A listing and description of the entire project documentation system and how they are related is contained in document FTR620100001, Project Overview.

The subcontractors and their contributing activities were as follows:

### TASK 4.2

#### Subcontractors

#### Role

Boeing Military Aircraft  
Company (BMAC)

Reviewer

D. Appleton Company  
(DACOM)

Responsible for IDEF support,  
state-of-the-art literature  
search

General Dynamics/  
Ft. Worth

Responsible for factory view  
function and information  
models



OM 620124001  
1 November 1985

Subcontractors

Role

Illinois Institute of  
Technology

Responsible for factory view  
function research (IITRI)  
and information models of  
small and medium-size business

North American Rockwell

Reviewer

Northrop Corporation

Responsible for factory view  
function and information  
models

Pritsker and Associates

Responsible for IDEF2 support

SofTech

Responsible for IDEF0 support

TASKS 4.3 - 4.9 (TEST BED)

Subcontractors

Role

Boeing Military Aircraft  
Company (EMAC)

Responsible for consultation on  
applications of the technology  
and on IBM computer technology.

Computer Technology  
Associates (CTA)

Assisted in the areas of  
communications systems, system  
design and integration  
methodology, and design of the  
Network Transaction Manager.

Control Data Corporation  
(CDC)

Responsible for the Common Data  
Model (CDM) implementation and  
part of the CDM design (shared  
with DACOM).

D. Appleton Company  
(DACOM)

Responsible for the overall CDM  
Subsystem design integration  
and test plan, as well as part  
of the design of the CDM  
(shared with CDC). DACOM also  
developed the Integration  
Methodology and did the schema  
mappings for the Application  
Subsystems.

OM 620124001  
1 November 1985

<u>Subcontractors</u>	<u>Role</u>
Digital Equipment Corporation (DEC)	Consulting and support of the performance testing and on DEC software and computer systems operation.
McDonnell Douglas Automation Company (McAuto)	Responsible for the support and enhancements to the Network Transaction Manager Subsystem during 1984/1985 period.
On-Line Software International (OSI)	Responsible for programming the Communications Subsystem on the IBM and for consulting on the IBM.
Rath and Strong Systems Products (RSSP) (In 1985 became McCormack & Dodge)	Responsible for assistance in the implementation and use of the MRP II package (PIOS) that they supplied.
SofTech, Inc.	Responsible for the design and implementation of the Network Transaction Manager (NTM) in 1981/1984 period.
Software Performance Engineering (SPE)	Responsible for directing the work on performance evaluation and analysis.
Structural Dynamics Research Corporation (SDRC)	Responsible for the User Interface and Virtual Terminal Interface Subsystems.

Other prime contractors under other projects who have contributed to Test Bed Technology, their contributing activities and responsible projects are as follows:

<u>Contractors</u>	<u>ICAM Project</u>	<u>Contributing Activities</u>
Boeing Military Aircraft Company (BMAC)	1701, 2201, 2202	Enhancements for IBM node use. Technology Transfer to Integrated Sheet Metal Center (ISMC)

OM 620124001  
1 November 1985

<u>Contractors</u>	<u>ICAM Project</u>	<u>Contributing Activities</u>
Control Data Corporation (CDC)	1502, 1701	IISS enhancements to Common Data Model Processor (CDMP)
D. Appleton Company (DACOM)	1502	IISS enhancements to Integration Methodology
General Electric	1502	Operation of the Test Bed and communications equipment.
Hughes Aircraft Company (HAC)	1701	Test Bed enhancements
Structural Dynamics Research Corporation (SDRC)	1502, 1701, 1703	IISS enhancements to User Interface/Virtual Terminal Interface (UI/VTI)
Systran	1502	Test Bed enhancements. Operation of Test Bed.

TABLE OF CONTENTS

		<u>Page</u>
SECTION 1.0	INTRODUCTION .....	1-1
SECTION 2.0	NECESSARY SYSTEM HARDWARE AND SOFTWARE .....	2-1
SECTION 3.0	CREATION OF IISS DIRECTORY .....	3-1
SECTION 4.0	SYSTEM LOGICALS .....	4-1
SECTION 5.0	INSTALLATION OF IISS: TAPE TO DISK ....	5-1
SECTION 6.0	SETTING ORACLE LOGICALS .....	6-1
SECTION 7.0	THE IISS BUILD .....	7-1
SECTION 8.0	CREATION OF IISS RUN AREA .....	8-1
SECTION 9.0	IMPORT TO THE ORACLE DATABASE .....	9-1

OM 620124001  
1 November 1985

## SECTION 1

### INTRODUCTION

This guide accompanies Release Tape 2.1 of IISS. It provides instructions for the building of IISS on a VAX. The tape was created with the following command: `BACKUP/VER IISS_CM:[IISS...]/EXCLUDE-(*.OBJ,*.OLB,*.EXE,*.MAI,[IISS.COM]*.*,[IISS.UTILITY]*.*,[IISS.MCMM]*.*) MT:IISS.BCK`

SECTION 2

NECESSARY SYSTEM HARDWARE AND SOFTWARE

The following system hardware and software should be sufficient for the installation and build of IISS. It is possible that lower versions of some software may be sufficient.

- VAX 11/780
- 4 Mb memory
- 80 Mb disk space for IISS
- 30 Mb disk space for ORACLE
- 1600 bpi tape drive
- 1 VT100 terminal
- 1 other terminal, any type
- VMS V3.7
- CDD V3.0
- DATATRIEVE V3.0
- ORACLE V4.2.2
- FORTRAN V3.5
- COBOL V3.0
- Interactive Systems UNIX Workbench V4.0

### SECTION 3

#### CREATION OF IISS

Create a new user [IISS], using the AUTHORIZE utility. This user should be given the default privileges NETMBX and TMPMBX plus in addition GRPNAM. The following parameters should be specified:

- PRCLM:32
- ENQLM:300
- TQELM:30
- BYTLM:99,000
- WSDEFAULT:200
- WSQUOTA:768
- WSEXTENT:2048
- BIOLM:12
- DIOLM:12
- FILLM:120
- PGFLQUOTA:50,000

Use the DISKQUOTA utility to set quotas for the new IISS user account. You will need 200,000 blocks on the IISS disk and 1000 blocks on the disk where ORACLE is installed if it is different.

OM 620124001  
1 November 1985

#### SECTION 4

#### SYSTEM LOGICALS

In your system startup command file, or your system login file, set the logical drive for [IISS] as IISS\_CM. This can be done with the following:

ASSIGN/SYSTEM \_drive: IISS\_CM



OM 620124001  
1 November 1985

SECTION 5

INSTALLATION OF IISS: TAPE TO DISK

The contents of the tape may be put to disk with the following:

BACKUP MT:IISS.BCK IISSCM:[\*...]/OWNER\_UIC=[x,y]  
where x,y is the UIC of your IISS account.

## SECTION 6

### SETTING ORACLE LOGICALS

The command files ORAUERL.COM and ORAUER.COM in [IISS.ORACLE] set ORACLE logicals for your site. You will need to edit these files to reflect the proper directories for your ORACLE installation. Prior to editing the files, ask your ORACLE database administrator the following:

1. Where was ORACLE 4.2 installed (drive:[directory])?
2. What environment symbol should be used for the new database environment? (This is a one-character arbitrary symbol that should be unique for your installation.)
3. What directory should be used for the new database environment (drive:[directory])? This is where the .DBS and .BI files will reside. It is likely that your ORACLE database administrator will want to set up a new account for this purpose.

In the two command files, ORAUERL.COM and ORAUER.COM, you will need to make substitutions in the first 17 lines that will depend on the above answers.

1. The answer to (1) should be substituted for any reference to OR41:[ORAC422].
2. The answer to (2) should be substituted for the following references to P:
  - The P in ASSIGN/GROUP P ORACLE\$SID
  - The P in PORACLE.DBS
  - The P in PORACLE.BI
3. The answer to (3) should be substituted for any reference to IISS\_PRODDB:[PRODORAP].

When you have finished editing the two command files, run your login file:

\$ @SYS\$LOGIN:LOGIN

## SECTION 7

### THE IISS BUILD

The command files for creating object libraries, compiling, linking, and so forth are located in [IISS.BUILD]. Once you have signed onto the IISS account, you will need to type the following:

```
$ SET DEF [IISS.BUILD]
$ SUBMIT/KEEP/NOTIFY BUILD.COM
```

Your build of IISS will be run as a batch job, with a log BUILD.LOG created under [IISS]. First the object libraries will be created and then each subsystem will be built (IPC, ERRLOG, NTM, COMM, UI, and CDM).

This batch job is likely to take a long time, perhaps eight hours or more, depending on the system load. The next step, "CREATION OF IISS RUN AREA", may not be done until the batch job finishes. You may however do the "IMPORT TO THE ORACLE DATABASE" at any time. When your batch job finishes, check the log file which will be automatically printed to see if all commands executed properly.

OM 620124001  
1 November 1985

## SECTION 8

### CREATION OF IISS RUN AREA

The area you will be running IISS from is [IISS.RUNAREA]. The directory is already created. You will need to move the necessary files to the directory, with the following:

```
$ SET DEF [IISS.BUILD]
$ @MOVERUN
```

## SECTION 9

### IMPORT TO THE ORACLE DATABASE

To run IISS, you will need to import the contents of the CDM, FORMS, and OO tables to an ORACLE database. Create an ORACLE database environment account with 60000 blocks of disk quota, as well as 2000 blocks of quota on the disk which contains the original installation of ORACLE 4.1. Once the ORACLE database environment account has been created, move all files under [IISS.ORACLE] to the account. First, when you are on [IISS], type the following:

```
$ SET DEF [IISS.ORACLE]
$ SET PROT-W:RE *.*
```

Then, log onto your ORACLE database environment account. Copy the oracle files to that directory and run the login file:

```
$ COPY IISS_CM:[IISS.ORACLE]*.* *
$ @LOGIN
```

The CDM, FORMS, and OO tables will require 30000 blocks for the .DBS file and 10000 blocks for the .BI file. To create the ORACLE database in the new database environment account, follow these procedures:

1. Be sure that you have at least 2000 blocks of disk quota on the disk which contains the original installation of ORACLE 4.1.
2. All ORACLE logicals, defined in [IISS.ORACLE]ORAUSERL, should point to the account which contains the original installation of ORACLE, except ORACLE\$DBS and ORACLE\$BI. These two logicals should point to the new ORACLE environment account.
3. Having logged onto the new ORACLE environment account, create the database files:

```
$ CCF xORACLE.DBS 30000
$ CCF xORACLE.BI 10000
```

here x is the unique environment symbol chosen to represent this database environment. Be sure that the logicals ORACLE\$DBS and ORACLE\$BI in ORAUSERL.COM

OM 620124001  
1 November 1985

point to these files.

4. \$ IOR INIT  
YES
5. \$ UFI @SYS\$ORACLE:CATALOG.ORA
6. \$ @SYS\$ORACLE:HELPINS  
YES
7. \$ @SYS\$ORACLE:CRTINS  
VT100
8. Log off the account and then log back on.
9. \$ UFI SYSTEM/MANAGER  
  , START V4EXP  
  , EXIT
10. \$ UFI SYSTEM/MANAGER  
  , GRANT RESOURCE, CONNECT TO CDM IDENTIFIED BY CDM;  
  , GRANT RESOURCE, CONNECT TO FORMS IDENTIFIED BY  
  FORMS;  
  , GRANT RESOURCE, CONNECT TO OO IDENTIFIED BY OO;  
  , EXIT

NOTE: In steps 10-12 you will be importing the different users of the database. The import creates tables, inserts data into tables, and creates indexes. You will see activity for the create tables and data being inserted. However, nothing is displayed during the creation of indexes. There may be a long pause where there appears to be no activity -- based on the system load at time of import. This is normal. The CDM import is likely to take more than one hour.

11. \$ IMP CDM/CDM  
  ORCDM.BCK  
  Y  
  Y  
  Y
12. \$ IMP FORMS/FORMS  
  ORFORMS.BCK  
  Y  
  Y  
  Y

OM 620124001  
1 November 1985

13. \$ IMP OO/OO  
OROO.BCK  
Y  
Y  
Y

14. \$ VSIMP ORCDM.VEW CDM/CDM

15. \$ VSIMP ORFORMS.VEW FORMS/FORMS

There are no views for OO. All the ORACLE information  
necessary to run IISS should now be in place.

END

7-87

DTIC